

## Richard Thompson

---

**From:** Scott McManus <smcmanus@teamgfa.com>  
**Sent:** Thursday, November 30, 2017 10:55 AM  
**To:** Richard Thompson  
**Cc:** beesonconsulting@outlook.com  
**Subject:** Fwd: TestAmerica report and EDD files from 680-144611-2 South Street Site (HAA)  
**Attachments:** 680-144611-2\_FLPivot.xls; ATT00001.htm; J144611-2 UDS Level 2 Report Final Report.pdf; ATT00002.htm

**This email came from outside of the City of Fort Myers, please be cautious opening attachments or clicking on links.**

Sent from my iPhone

Begin forwarded message:

**From:** "Savoie, Noel" <[noel.savoie@testamericainc.com](mailto:noel.savoie@testamericainc.com)>  
**To:** "Scott McManus" <[smcmanus@teamgfa.com](mailto:smcmanus@teamgfa.com)>  
**Subject:** TestAmerica report and EDD files from 680-144611-2 South Street Site (HAA)

Hello,

Attached please find the report and EDD files for job 680-144611-2; South Street Site. When I asked the lab how a sample could go from having such a high hit for MCAA to nondetect and he said the most common was contamination in the field from the containers for method 531, which are preserved with MCAA. I was told beyond that theory they were not sure.

Please feel free to contact me if you have any questions.

Thank you.

Please let us know if we met your expectations by rating the service you received from TestAmerica on this project by visiting our website at: [Project Feedback](#)

**NOEL SAVOIE**  
Project Manager

**TestAmerica**  
THE LEADER IN ENVIRONMENTAL TESTING

Tel: 850.878.3994  
[www.testamericainc.com](http://www.testamericainc.com)

Reference: [393892]

